

Monitoring Data Record

Project Title: B-3126 (Br. #90 over Gunpowder Creek on SR 1718)

COE Action ID: 2007-1591-214

DWQ Number: 070583

Stream Name: Tributary to Gunpowder Creek

City, County and other Location Information: Caldwell County, Bridge #90 over Gunpowder Creek on SR 1718(Deal Mill Road) near Granite Falls..

Date Construction Completed: 3/11/09 Monitoring Year: (1) of 5

Ecoregion: _____ 8 digit HUC unit 03050101

USGS Quad Name and Coordinates: Granite Falls N 35.84415, W 81.43603

Rosen Classification: Proposed C5 Stream Type

Length of Project: 315' Urban or Rural: Rural Watershed Size: _____

Monitoring DATA collected by: M. Green Date: 9/30/09

Applicant Information:

Name: NCDOT Roadside Environmental Unit

Address: 1425 Rock Quarry Road Raleigh, NC 27610

Telephone Number: (919) 861-3772 Email address: mlgreen@ncdot.gov

Consultant Information:

Name: _____

Address: _____

Telephone Number: _____ Email address: _____

Project Status: Complete

Monitoring Level required by COE and DWQ (404 permit/ 401 Cert.): Level 1 2 3

Monitoring Level 1 requires completion of *Section 1, Section 2 and Section 3*

Permit States: (COE Permit Requirements): The permittee shall perform the following components of Level I monitoring each year for the 5-year monitoring period: Reference photos; plant survival (i.e., identify specific problem areas (missing, stressed, damaged or dead plantings), estimated causes, and proposed/required remedial action); visual inspection of channel stability. Physical measurements of channel stability/morphology will not be required. The permittee shall submit the monitoring reports to the Corps of Engineers, Raleigh Regulatory Field Office Project Manager, within sixty days after completing the monitoring. If less than two bankfull events occur during the first 5 years, the permittee shall continue monitoring until the second bankfull event is documented. The bankfull events must occur during separate monitoring years. In the event that the required bankfull events do not occur during the five-year monitoring period, the Corps of Engineers, in consultation with the resource agencies, may determine that further monitoring is not required. It is suggested that all bankfull occurrences be monitored and reported through the required monitoring period. The permittee shall perform and submit photo documentation twice each year (summer and winter) for the 5-year monitoring period, and for any subsequently required monitoring period.

(DWQ Permit Requirements): The permittee shall visually monitor the vegetative plantings to assess and ensure complete stabilization of the mitigation stream segments. The monitoring shall be conducted annually for a minimum of three (3) years after final planting. Photo documentation should be utilized to document the success of the riparian vegetation and the results submitted in a final report to DWQ within sixty (60) after completing the monitoring. After three (3) years a site visit shall be conducted by DWQ staff to "close out" the mitigation site.

Section 1. PHOTO REFERENCE SITES

(Monitoring at all levels must complete this section)

Total number of reference photo locations at this site:

6 photos were taken from 3 photo point locations

Dates reference photos have been taken at this site: 9/30/09

Individual from whom additional photos can be obtained (name, address, phone): _____

Other Information relative to site photo reference: A site map with photo point locations is included with this report.

If required to complete Level 3 monitoring only stop here; otherwise, complete section 2.

Section 2. PLANT SURVIVAL

Attach plan sheet indicating reference photos.

Identify specific problem areas (missing, stressed, damaged or dead plantings):

Estimated causes, and proposed/required remedial action: _____

ADDITIONAL COMMENTS: Planted vegetation is surviving along the streambank and within the buffer area. Streambank reforestation included American Sycamore, Yellow Poplar, River Birch, Black Cherry, Black Willow, Silky Dogwood. Other vegetation noted: lespedeza, pokeberry, Juncus.sp., white oak, and various grasses.

If required to complete Level 1 and Level 2 monitoring only stop here; otherwise, complete section 3.

Section 3. CHANNEL STABILITY

Visual Inspection: The entire stream project as well as each in-stream structure and bank stabilization/revetment structure must be evaluated and problems addressed.

Report on the visual inspection of channel stability. Physical measurements of channel stability/morphology will not be required. Include a discussion of any deviations from as-built and an evaluation of the significance of these deviations and whether they are indicative of a stabilizing or destabilizing situation.

Tributary to Gunpowder Creek is stabilized for the Year 1 Summer evaluation except for two crossvanes that have water piping under them within the step pool area. NCDOT will continue to monitor the stream relocation.

Date 9/30/09	Station Number 2+40-NSD-	Station Number 3+00-NSD-	Station Number	Station Number	Station Number
Structure Type	Crossvane	Crossvane			
Is water piping through or around structure?	Water was piping under crossvane	Water was piping under crossvane			
Head cut or down cut present?					
Bank or scour erosion present?					
Other problems noted?					

Tributary to Gunpowder Creek



Photo Point #1 (Upstream)



Photo Point #1 (Downstream)



Photo Point #2 (Upstream)



Photo Point #2 (Downstream)



Photo Point #3 (Upstream)



Photo Point #3 (Downstream)

B-3126 GUNPOWDER CREEK LITTLE PHOTO LOCATIONS

⊕ - PHOTO POINT LOCATIONS

APPROX. LOCATION
WAS NOT DESIGNATED
UTILITY REP. POINTED
OUT AREA OF CROSSING

CLASS. HRP RAP
STRUCTURE NEW

END STREAM RELOCATION
STA 315 = STA 1841 L-

SEE DETAIL SH. 25

SEE DETAIL SH. 26

SEE DETAIL SH. 27

SEE NOTE 1

BL-3 POS 20+30.5

BL-PK 23+13.25

BL-3 POS 20+30.5

BL-PK 23+13.25

BL-3 POS 20+30.5

BL-PK 23+13.25

BL-3 POS 20+30.5

BL-PK 23+13.25

BL-3 POS 20+30.5

BL-PK 23+13.25

BL-3 POS 20+30.5

BL-PK 23+13.25



Standard
Engineering
Company, Inc.
1000 North 10th Street
Tulsa, Oklahoma 74103
Tel. (918) 436-1111
Fax (918) 436-1112

CONS. I. REV.
DATE
BY
CHKD.
DATE
BY